



rank of windows near the northeast corner; the windows are two-over-two units that may be original. The south elevation has a similar appearance to the north elevation. The molded cornice with its frieze and returns is visible above. The wall surface is clad with wood clapboards. Fenestration is aligned vertically and horizontally; windows are two-over-two wood sash units (possibly original).

The rear additions are barely visible from the public right-of-way. The two-story rear addition is aligned with the north end of the main block. It has a shed roof and a chimney near the center. The one-story rear addition wraps around the west and south elevations of the two-story addition.

Character-defining features of the dwelling include painted louvered shutters and a one-story front porch with turned spindles and decorative brackets.

History: The 1916 Sanborn Atlas shows the main block of the house and a two-story rear addition that is smaller than the current section. A small outbuilding behind the house had disappeared by the time of the 1933 Sanborn Atlas. The latter atlas shows the rear two-story addition as it currently appears. A new outbuilding is shown in the far reaches of the lot. Historic aerials depict the house beginning in 1940. The main block and two-story rear addition appear on all aerials. The one-story addition was built in sections, and it was not fully depicted on aerials until 2012.

**Setting:**

The Sarah Disbrow House at 19 North Main Street is sited on a rectangular parcel (Block 23, Lot 65) located on the west side of North Main Street in Cranbury Township, Middlesex County, New Jersey. The building is oriented with its primary elevation facing southeast and is set back approximately 10 feet from North Main Street.

The portion of the sidewalk that spans the east side of the parcel is paved with bricks. A brick driveway leads west from North Main Street to a gravel parking lot. The property is lightly wooded to the rear (west) of the property. 19 North Main Street is located in a mixed residential and commercial neighborhood surrounded by properties dating from the mid-nineteenth to the early twentieth century.

**Registration and Status Dates:**

National Historic Landmark?:

National Register: 9/18/1980

New Jersey Register: 8/9/1979

Determination of Eligibility: 3/25/1977

Certification of Eligibility:

SHPO Opinion:

Local Designation: 9/26/1988


Other Designation:

Other Designation Date:

Eligibility Worksheet included in present survey?

Is this Property an identifiable farm or former farm?

**Location Map:**



**Site Map:**

**BIBLIOGRAPHY:**

Survey Name: Cranbury CLG Survey 2017

Surveyor: Kristen Herrick

Organization: RGA, Inc.

Property ID:

**-208130644**

Page 2

(Primary Contact)

Author:	Title:	Year:	HPO Accession #:
Walsh, Ruth	National Register of Historic Places Nomination for the Cranbury Historic District, Cranbury Township, Middlesex County, New Jersey	1979	(if applicable)
Heritage Studies	Preserving Historic Cranbury Village	1989	
Cranbury Historical and Preservation Society	Chain of Title, 19 North Main Street		

**Additional Information:**

The 1989 Heitage Studies survey identified the Sarah Disbrow House at 19 North Main Street as a contributing resource to the Cranbury Historic District. RGA concurs with the previous evaluation and recommends the Sarah Disbrow House at 19 North Main Street due to its date of construction and design.

**More Research Needed?**  (checked=Yes)

**INTENSIVE-LEVEL USE ONLY:**

**Attachments Included:**

0 Building	0 Bridge
0 Structure	0 Landscape
0 Object	0 Industry

**Historic District ?**

**District Name:** Cranbury Historic District

**Status:** Contributing

**Associated Archeological Site/Deposits?**

(known or potential sites. If Yes, please describe briefly)

Conversion Problem?  ConversionNote: 101

Date form completed: 6/26/2017

**Survey Name:** Cranbury CLG Survey 2017

**Surveyor:** Kristen Herrick

**Organization:** RGA, Inc.

**Property ID:**

(Primary Contact)

**-208130644**