

northeast, side elevation of the main block is lighted by 2 windows on the first floor and a single window on the second floor. The rear volume is lighted by a single window on the first floor and a double window on the second floor of the northwest elevation and by a single window and 3 double windows on the northeast elevation. The southeast, rear elevation is asymmetrically fenestrated.

South Main Street includes some of the earliest development in Cranbury. The settlement began in 1736 with the construction of a mill on the south banks of the Cranbury Brook and, by 1810, developed into a small village. The 1980 National Register of Historic Places Nomination for the Cranbury Historic District indicates that the 2-story, frame residence with a center entrance at 35 S. Main Street was built in the mid-19th century. The 1989 Heritage Studies Inventory reports that a plaque on the residence dates it to 1820, but that the small windows on the north end of the main elevation suggest an earlier construction date for part of the dwelling. Historic maps indicate that a residence owned by "N. Rue" was built on the property by 1876. A historic photograph taken circa 1890 depicts the building as the Rue residence and bootmaker's shop. The clapboard clad building is fronted by a full-length, composite-roofed porch with square-plan posts, and is lighted by 6/6 windows. In the southwest bay is a projecting, 12-light display window and a 4-light door. This evidence suggests that the bootmaker's shop was located in the southwest bays of the building and the residence located in the northeast bays (Brennan and Brennan, 1995: 19). The 1916 Sanborn Map documents the building as a 2-story, rectangular-plan, frame dwelling fronted by a 1-story, partial-width porch and backed by a 1-story, partial-width rear volume with a projecting bay. A 2-story secondary dwelling, now 3 Station Road, is also documented as part of the lot. The 1933 Sanborn Map documents the same massing of the dwelling. The 1974 photographic inventory of Cranbury historic buildings in the collection of the Cranbury Historical and Preservation indicates that the front porch was replaced by a pedimented door hood with shaped brackets sometime in the mid-20th century. This image also documents the residence as having a 3-light door, 6/6 sash windows, and a standing seam metal roof. Visual evidence suggests that the door, window sash, and roofs have been replaced within the last ten years.

This is a contributing property in the Cranbury Historic District because it retains integrity and historic, character-defining features such as the historic massing and historic fenestration patterns of the main volume.

Setting:

South Main Street stretches from Brainerd Lake to the southern edge of Cranbury and is characterized by freestanding single-family residences of moderate scale ranging in date from the early 19th century to the early 20th century.

Registration and Status Dates:

National Historic Landmark?:

National Register: 9/18/1980

SHPO Opinion:

New Jersey Register: 8/9/1979

Local Designation: 9/26/1988

Determination of Eligibility: 3/25/1977

Other Designation:

Certification of Eligibility:

Other Designation Date:

Eligibility Worksheet included in present survey?

Is this Property an identifiable farm or former farm?

Survey Name: Cranbury Local Historic District Survey 2018

Property ID:

Page 2

Principal Investigator: Emily Cooperman


(Primary Contact)

-1460589352

Organization: Paulus, Sokolowski & Sartor

Location Map:

Site Map:



BIBLIOGRAPHY:

Author:	Title:	Year:	HPO Accession #: (if applicable)
(None Listed)	1850 Otley and Keily Map	1850	
(None Listed)	1933 Sanborn Map	1933	
Brennan, Peggy and Frank J. Jr.	Images of America: Cranbury, Volume II	1998	
(None Listed)	1876 Everts and Stewart Map	1876	
Walsh, Ruth	National Register of Historic Places Nomination for the Cranbury Historic District, Cranbury Township, Middlesex County, New Jersey	1979	
(None Listed)	Aerial and street view photography for 1931, 1940, 1947, 1953, 1957, 1963, 1969, 1970, 1972, 1979, 1987, 1995, 2002, 2006, 2007, 2008, 2010, 2012, 2013, and 2015 available at historicaerials.com and for 1995, 2002, 2006, 2007, 2008, 2010, 2013, 2016, and 2017 available through Google Earth		
Heritage Studies	Preserving Cranbury Township	1989	
Brennan, Peggy and Frank J. Jr.	Images of America: Cranbury	1995	
Chambers, John Whiteclay II	Cranbury: A New Jersey Town from the Colonial Era to the Present	2012	
(None Listed)	1916 Sanborn Map	1916	

Additional Information:

1202_35_12 / 2STY - SFD / 1780

More Research Needed? (checked=Yes)

Survey Name: Cranbury Local Historic District Survey 2018

Principal Investigator: Emily Cooperman

Organization: Paulus, Sokolowski & Sartor

Property ID:

-1460589352

(Primary Contact)

INTENSIVE-LEVEL USE ONLY:

Attachments Included: 0 Building 0 Bridge
 0 Structure 0 Landscape
 0 Object 0 Industry

Historic District ?

District Name: Cranbury Historic District

Status: Contributing

Associated Archeological Site/Deposits?

(known or potential sites. If Yes, please describe briefly)

Conversion Problem? ConversionNote:

Date form completed: 8/24/2018

Survey Name: Cranbury Local Historic District Survey 2018

Principal Investigator: Emily Cooperman

Organization: Paulus, Sokolowski & Sartor

(Primary Contact)

Property ID:

-1460589352